

Audit Report

For

Egyptian Ship Repair & Building Company (Ministry of defense)

Surveillance 2 (SV2)

Audit Dates: 17/11/2024 to 18/11/2024

Organization Details

Company: Egyptian Ship Repair & Building Company (Ministry of defense)

Address: Gate #1, Custom Zone, Alexandria, Egypt

Contact Person: Ossama Mohamed

Email: quality@esrbc.net

Audit Criteria: ISO 9001:2015 / ISO 14001:2015 / ISO 45001:2018

EA Code: 20,29

Scope: Ship building, repair and maintenance Steel structure manufacturing

Critical spare part fabrication (propellers, propellers shaft, rudders,

rudder stock, coolers)

Audit Objectives

Surveillance audits are on-site audits, but are not necessarily full system audits, and shall be planned together with the other surveillance activities so that GCB can maintain confidence that the client's certified management system continues to fulfil requirements between recertification audits. Each surveillance for the relevant management system standard shall include:

- a) internal audits and management review;
- b) a review of actions taken on nonconformities identified during the previous audit;
- c) complaints handling;
- d) effectiveness of the management system with regard to achieving the certified client's objectives and the intended results of the respective management system(s);
- e) progress of planned activities aimed at continual improvement;
- f) continuing operational control;
- g) review of any changes;
- h) use of marks and/or any other reference to certification.

Auditors

Auditor Name	Role
Adel Belal	Lead Auditor
Ahmed Keshk	Auditor
Mohamed Fouad	Auditor
Islam Abdallah	Auditor

Auditee Members

Auditee Name	Position
Amr Hassanin (opening, closing, interview)	HR & Training
Mr. Wael Mansour Abdelhadi (interview)	HSE Staff
Mohamed Salah (interview)	Planning Staff
Sameh Abdelhamid (opening, closing, interview)	HD of OCC. Health
Mohamed Rabie (interview)	Quality Staff
Ola Salah (interview)	Planning Staff
Osama Mohamed Ahmed (opening, closing, interview)	QC Manager
Hesham Shehata Ibrahim	Purchasing Staff

No. of Man-Days
8.0

Audit Findings

Clause No.	Requirement\\Departement	Evidence	Result
4.1	Understanding the organization and its context	ISSUE RELATED TO EACH DEPARTMENT HAS BEEN REVIEWED AS CHANGING TEMPERATURE AND ITS IMPACT ON DELAY SOME ACTIVITIES. THE ISSUE SHOWS RELATION TO DEPARTMENT ACTIVITIES, ASPECTS AND HAZARDS. THE ISSUES DEFINED NEED TO BE ENHANCED TO CLEARLY REFLECT THEM TO BUSINESS.	ОК
4.2	Understanding the needs and expectations of workers and other interested parties		OK
4.3	Determining the scope of the QMS, EMS and OHSMS	Company has defined the scope related to its IMS as defined on the application. The scope has been verified through the planning and implementation cheek.	ОК

Clause	Requirement\\Departement	Evidence	Result
No. 4.4	QMS, EMS and OHSMS and their	The process approach has been reviewed	OK
4.4	processes	for each department. The process related to	
	processes	IMS has been observed, the input, output,	
		resources, control and KPI. The process	
		•	
		approach needs to be enhanced to ensure	
		the integration of the QMS, EMS and	
F 4	Landard Sanada and Sanad	OHSMS within the business process.	01/
5.1	Leadership and commitment	Top management commitment has been	ОК
		observed during the audit, by providing all	
		possible recourses as well as attend the	
		opening and closing meetings	
5.2	Quality, Environment and health & safety	The integrated management policy (EMS	OK
	policy	and OHSMS) policy has been reviewed and	
		observed that no clear commitment to fulfil	
		its environmental compliance obligations.	
5.3	Organizational roles, responsibilities and	Responsibilities for Environment are not	OK
	authorities	clearly defined, Job descriptions for the IMS	
		have been reviewed for different position	
		related to the IMS different responsibilities.	
		The job descriptions not clearly reflect the	
		actual experience, skills, and knowledge	
		within employees and need to be more	
		precise specially in environment. During the	
		reviewing Job description of (Welder) and	
		(HSE manager), found that it did not reflect	
		clearly to real competence of employees	
		working in these positions as it define those	
		conditions to fill welder position is to follow	
		·	
		at least 17 years of experience to be	
		competent which is not applicable for	
		Welder Elsaid Ali Mohamed. and the	
		environmental responsibilities for HSE roles	
		are not defined.	014
5.4	Consultation and participation of workers	Company defined clearly the participation	OK
		and consultation of workers Evidence	
		participation in firefighting training dated	
		26/1/2024 Evidence in workers consultation	
		in Risk assessment for cutting and welding.	
			1

Clause	Requirement\\Departement	Evidence	Result
No.			1014
6.1	Actions to address risks and opportunities	Company defined environmental aspect and	IOK
		impact as metal forming workshop; aspect	
		was growth of bacteria and fungi in damp	
		areas and their impact was health issues	
		and contamination and the was evaluated	
		as medium risk, and company has defined	
		significant impact as respiratory issues for	
		workers from welding emissions.	
		Opportunities are not Cleary defined on	
		environmental issues. Legal registers for	
		the law 4/ 1994 need to be clearly identified.	
6.2	Quality, environment and health & Safety	The company has defined many objectives	NC
	objectives and planning to achieve them	to be achieved this year, such as protecting	
		environment from pollution and harmful	
		emissions. All objectives' plans have been	
		reviewed with defined achievement criteria.	
		Some objectives based on applicable	
		requirements like to comply with ISO	
		9001:2015, ISO 14001:2015 and ISO	
		45001:2018, or applicable with legal	
		requirements	
6.3	Planning of changes	COMPANY NEEDS TO CLARIFY M.O.CS	OK
		AS IT'S ONLY ONE MOC FROM	
		PREVIOUS YEARS IN APPLYING	
		ADDITIONAL MECHANICAL	
		VENTILATION INSIDE ALUMINUM	
		WORKSHOP.	
7.1	Resources	- Resources are clearly defined in a	NC
		purchasing order for personal protective	
		equipment's (PPEs) dated 27/8/2024	
		- calibration of wire 58mm d. 200mm l.	
		1960N/mm2 used in test need to be	
		calibrated	
7.2	Competence	Evidence of competence are defined as	ОК
		welder Elsaied Ali Mohamed joining date	
		14/10/2008 has a certificate from DNV	
		Welder's qualification test certification	
		issued on 28/8/2024 and valid to 28/8/2026	
		upon code of testing ISO9606-1	
		Radiographic / Ultrasonic (type of test) and	
		a training request from legal department to	
		schedule a NAPC course with EMEND	
		training agent from 13/02/2024 to	
		26/05/2024. Trainees pass the course test	
		on 18/7/2024 as Eng Walled Saber and Eng	1
		Osama Adm.	

Clause	Requirement\\Departement	Evidence	Result
No.	-		
7.3	Awareness	SAFETY AWARENESS HAVE BEEN	OK
		CONDUCTED TO SEVERAL	
		DEPARTMENT AS PRESERVATION	
		DEPARTMENT ON FIREFIGHTING	
		PROCESSES.	
7.4	Communication	Communication has been confirmed is	OK
		safety communication form No.1	
		internal and external communication.	
7.5	Documented information	Internal and external issues list &interested	NC
		parties requirement list not controlled	
		ACCORDING to the company doc.controller	-
8.1	Operational planning and control	Clarified in the control measures in ship	OK
ı		repair and construction dated 1/10/2021	
8.2	Determination of requirements for products	The company has conducted many drills	ОК
i	and services and	regarding the Environment such as oil	
	Emergency preparedness and	spilling drill on ship and open and cut the	
ı	response	bottom of the syringe and slide the waste of	
		prolitic material on the floor of the basin	
		3/10/2024	
		Customer requirements (red sea port	
		Technical offer 1/829 dated 22/8/2021 for	
0.2	Design and development of products and	safaga2	OK
8.3	Design and development of products and	This clause is excluded due to the company	UK
	services	activities which doesn't	
		include any design activity. The company	
		receives the design and manufacturer	
		according to design and class supervision.	211
8.4	Control of externally provided	NA	OK
	processes, products and		
	services		
8.5	Production and service provision	During the site visit the production	OK
		operations has been checked as a sample	
		from the design layout drawing and building	
		the fixtures to build	
		the required tug body piece number	
		according to the detailed drawing.	
		Documented information:	
		Workshop drawing 3518-100-21S1R3	
		ALIGNMENT REPORT OF PROPELLER	
		SHAFT WITH TURBO COUPLING AFTER	
		CHOCK FAST QC HULL163	
8.6	Release of products and services	Inspection report VT& Dimensions QC8	ОК
	Transfer of production and controls	29/7/2024 BOLLARD PULL TRIM LOAD	[
		CASE FOR P999TRIALS	
8.7	Control of nonconforming outputs		ОК
0.1		NCR determined by the inspector (1 23 / 10	
		• • • • • • • • • • • • • • • • • • • •	
		(23)	

Clause No.	Requirement\\Departement	Evidence	Result
9.1	Monitoring, measurement, analysis and evaluation	Clified in multi gas detector calibration No. C819. KPI report for (SAFAGA 2) duration from	ОК
9.2	Internal audit	1/1/2024 – 30/8/2024. The internal audit program has been reviewed issued on 7/9/2024 for safety requirement but environmental requirements are not defined clearly on audits checklists, and sample of the audits conducted have been reviewed. dated 11/09/2023 on Mechanical workshops. The IA program doesn't clearly define how the frequencies of auditing have been determined.	NC
9.3	Management review	QMS INTERNAL AUDIT team did not achieve Impartiality Defined and clarified in managers meeting	ОК
10.1	General	dated 15/10/2024. The company top management has been	ОК
		observed to do his best to improve the service of the company include the infrastructure improvement. The company start to communicate on Egypt vision for 2050 for carbon footprint.	
10.2	Nonconformity and corrective action	Needs to be clarified As reviewed an incident of worker (Mohamed Ahmed Elsayed) dated 30/7/2024, but no corrective actions have been addressed. The Root Cause in some NCRS are identified by the auditor	ОК
10.3	Continual Improvement	Defined and clarified through light intensity measurement in 2023 below the allowable limits, But in 2024 next light intensity measurements are adequate	ОК
	Use of Logo	The company has established a tool of improvement through the policy, objectives, IA, management review and corrective action	OK

Strength Point

- Top management commitment.
- Top management commitment has been observed during the audit, by providing all possible recourses as well as attend the opening and closing meetings.
- The company top management has been observed to do his best to improve the service of the company include the infrastructure improvement.
- Work instructions are simple and well distributed for different machines.
- Good distributions for safety signs and emergency exist.
- Well distribution for fire extinguishers.
- Suitable covers are applied for machines rotating parts.
- Good natural and Mechanical ventilation inside workshops.

Observation

- Defined interested parties need to be enhanced as well as the requirements need to be clearer.
- The integrated management policy (EMS and OHSMS) policy observed that no clear commitment to fulfil its environmental compliance obligations.
- Responsibilities for Environment are not clearly defined.
- Job description did not clearly reflect to real competence of employees working in these positions.
- Legal registers for the law 4/ 1994 need to be clearly identified.
- Environmental requirements are not defined clearly on audits checklists.
- Need to clarify the risk and the opportunity in the analysis methods.
- Objectives for safety are not smart.
- Evidence of the corrective actions taken after an incident or near miss needs to be clarified

Minor NCR

- (6.2.1.c) Some quality objectives based on applicable requirements like to comply with ISO 9001:2015, ISO 14001:2015 and ISO 45001:2018, or applicable with legal requirements
- (7.1.5.1) Certificate of calibration of wire D=58mm L=200mm St=1960N/mm2 was not available during the audit
- (7.5.2.a) Internal and external issues list &interested parties requirement list not controlled ACCORDING to the company doc.controller
- (9.2..2.c) QMS INTERNAL AUDIT team did not achieve Impartiality

Team Leader Recommendations

The management system of the organization being audited, is recommended to SV2 of

Disclaimer Statement

The judgment of the management system is based on the sample shown during the audit time.

Lead Auditor Name:

Adel Belal Signature