

Audit Report

For

NEFERTITI MARINE

Stage 2

Audit Dates: 13/08/2025 to 14/08/2025

Organization Details

Company: NEFERTITI MARINE

Address: 1 El Ferdous St. Smouha Alexandria,

Contact Person: Eng. Karim Abd El Karim

Email: karim@nefertitimarine.com

Audit Criteria: ISO 9001:2015

EA Code: EA 20

Scope: Ship building & repair, Ship design and marine trading

No. of Sites:

Sites

Site Name	Location
Workshop	YARD K Rosetta Coast, Egypt

Audit Objectives

- 1- To confirm that the organization's Quality Management System (QMS) is fully implemented as per the ISO 9001 requirements.
- 2-To verify that all processes, controls, procedures, and policies documented in the management system are being followed and are effective.
- 3-To assess the actual effectiveness of the QMS in meeting the organization's quality objectives and compliance with the standard.

Auditors

Auditor Name	Role
Mohamed Abdellatif	Team Leader
Adel Belal	Observer

Auditee Members

Auditee Name	Position
Eng.Karim (opening and closed meeting)	Managing Director
Eng. Mohammad Medhat (opening and closed meeting)	QA Engineer

Eng.Mohsen Ali Yehia (opening and closed meeting)	Technical Manager
Eng. Reham Ezzat (opening and closed meeting)	QA Manager
Eng. Mohab Ashraf (opening meeting)	Design Engineer
Eng. Hesham Ahmed Said (opening meeting)	Project Manager
Ebrahim Mohamed Hossen	Welder

No. of Man-Days
2.0

Audit Findings

Clause	Requirement\\Departement	Evidence	Result
No.			
		Training plan NM-QMS P05-F08 (4) training courses have been implemented for Eng. Mohab Ashraf (Construction-Piping and machinery for marine vessels-Rhino-Shipyard Technology) from July- September 2025.	

Clause No.	Requirement\\Departement	Evidence	Result
	Design department	for KASID KHEIR Sample the following	OK
.2.,7.2 8.3		documents are reviewed to ensure design	
		validation and verification in addition to	
		methodology for design KPI calculation (one	
		modification have been observed for 22	
		total drawing.	
		lotal drawing.	
		I 1- Design Procedure NM-QMS-	
		P08.including design validation - verification	
		responsibilities and criteria of KPI	
		calculation.	
		2-Design Plan NM-QMS-P08-	
		F01	
		3- Design Input Checklist NM-	
		QMS-P08-F02.including all customer	
		requirements and list of drawing needed .	
		4- Design Change Request	
		NM-QMS-P08-F04 include production	
		feedback as an origin for change request	
		dated 18/3/2025 - 2 drawings will be	
		affected in hull construction (N25-50MPON	
		TOON-007-N25-50MPONTOON-005)	
		change has been approved by Moustafa	
		Khamis as Design Lead and Karim Abdel-	
		Karim as Managing Director .	
		Maxsurf software 2021 have been used in	
		design validation while Rhino -7 software	
		2020 is used for design verification process.	
		5- design risks have been established NM-	
		QMS-P02-F03 risk register two risks are	
		observed (Critical Structural or Stability	
		Miscalculations with Implement a peer	
		review system for all structural and stability	
		calculations by the design lead corrective	
		action) also another risk (Non-Compliance	
		with Maritime Regulations or Classification	
		Rules) with Maintain and regularly update a	
		regulatory requirements database corrective	
		action.	
		6- N25-50m PONTOON-015 DWG have	
		been checked designed by Eng. Habiba	
		salah-checked byEng.Moustfa Khamis-	
		Approved by Eng. Karim Abd EL Karim .no	
		design review has been done.	

Clause No.	Requirement\\Departement	Evidence	Result
No.	Requirement\\Departement Purchasing	the following purchasing documents have been reviewed. 1-Approved vendor list NM-QMS-P13-F04 has been reviewed with 25 local vendor for example ELHAMD company supplier. 2-Supplier evaluation NM-QMS-P13-F03 has been checked for example ESWECO for welding electrode delivery. 3- one risk has been established NM-QMS-P02-F03 risk register (Delay in steel delivery from Sole supplier) with corrective action Use early procurement planning	Result OK
		during the project kickoff stage. 4-NM-QMS-P13-F02 Purchase Order (P.O) Supplier Name-ESWECO for 6 different welding electrode dated 21/7/2025.	
8.5,4.1,4.2	Ship building	for KASID KHEIR Sample 1- NDT NM-QMS - P15-F04 visual inspection test report including 6 welding process in 6 different sections for midship section with accepted results .test date 7/4/2025. 2- NM-QMS-P15-F05 Pressure test log dated 9/4/2025 for 21 tank with no observation for (leak/drop)-test type pneumatic test. 3- Work Instructions NM-QMS-P15-W01. 4- Asset Register & Maintenance Plan NM-QMS-P06-F01. 5- Production procedures NM-QMS-P15. 6- two risks have been observed in risk register NM-QMS-P02-F03.	OK

Clause	Requirement\\Departement	Evidence	Result
No.			
	Warehouse	2- delivery request NM-P04-	ОК
.5.4		F03.four different materials have been	
		requested through production department	
		dated 9/8/2025.	
		3-Warehouse Management	
		Procedure NM-QMS-P04.	
		welding electrode have been	
		checked with:	
		batch no sqy210520-30	
		Manfacturing date 15/06/2024.	
		4- Warehouse Keeper	
		Competency NM-QMS-P05-F21 has been	
		checked .Employee Mohamed Zaghloul	
		assessment dated 23/7/2025 is observed	
		Technical Competency Checklist was	
		reviewed .the employee has meets	
		minimum competency requirements and	
		therefore no need for additional training, the	
		evaluation was approved with Eng. Hesham	
		Ahmed (Project Manager).	
8.5	Ship Repair	Maintenance works for the hull of Al-	OK
0.5	Only Repair	Jabbarah (13) has been issued from	
		1	
		ELNASR company for building and	
		construction with total (33)requirement .date 25/8/2025.	
		25/8/2025. 	

Clause No.	Requirement\\Departement	Evidence	Result
9.2,9.3	QA	1- NM-QMS-F02 Meeting Summary Report dated 28/7/2025 including (Review of Internal audit results-Customer feedback on KASED KHAIR B2 and MONSOON projects-Process performance and production delays-Status of nonconformities and corrective actions-Review of supplier performance and delivery delays-Evaluation of resource needs (equipment – manpower)-Risk and opportunity updates-Quality objectives progress – 1st and 2nd quarter). Action required for each topic has been documented attendance 1. Eng. Karim Abd El Karim 2. E ng. Nader Abd El Karim 3. Eng. Mohsen Ali 4. Eng. Reham Ezzat 5. Eng. Mohammad Medhat 2- Internal audit report NM-QMS-P11-F04 dated 10/7/2025 including (1) NCR (HR)	
9.1	QC	département. 1- NDT NM-QMS - P15-F04 visual inspection test report including 6 welding process in 6 different sections for midship section with accepted results .test date 7/4/2025. 2- NM-QMS-P15-F05 Pressure test log dated 9/4/2025 for 21 tank with no observation for (leak/drop)-test type pneumatic test. 3-Thordon propeller shaft bearing installation report NM-QMS-P09-F06 dated 15/4/2025 accepted by Eng. Mostafa Ragab	

Clause No.	Requirement\\Departement	Evidence	Result
8.2	Marine supplies.	Thordon Propeller Shaft Bearing Installation Report. NM-QMS-P09-F06 1. Date of Installation: 2. Thordon Distributor: 15/04/2025 NEFERTITI MARINE 3. Location (Shipyard/Dock): SUMED Bearing Installation Acceptance Date of Arrival: 14/04/2025 Date of Release: 15/04/2025 Accepted by: Eng. Mostafa Ragab	OK

Strength Point

- 1- Full implementation of the Quality Management System (QMS) is evident and aligns with ISO 9001 requirements.
- 2- The management system is effective in achieving organizational quality objectives and demonstrating continual improvement.
- 3- Preventive and corrective actions are properly identified, documented, and followed up, showing proactive handling of nonconformities.
- 4-Compliance with all applicable statutory and regulatory requirements.
- 5-Risk-based thinking and opportunities for improvement are integrated into the system, promoting a culture of continuous improvement.
- 6-Evidence of strong leadership and commitment from top management in supporting and promoting the QMS.

Area for Improvement

Root cause analysis deeply when address the issues without focusing only on symptoms.

Observation

- 1-No clear evidence for pressure gauge calibration used during pressure test.
- 2- External provider selection criteria need to identify more clearly.
- 3- No clear evidence for QC qualification.

4- No clear evidence for level-2 certification related to visual inspection test (NDT)
Minor NCR
NA
Major NCR
NA
Team Leader Recommendations
Nefertiti Company introduced sufficient evidence for providing ISO 9001 certification.
Disclaimer Statement
The judgment of the management system is based on the sample shown during the audit time.
Lead Auditor Name: Mohamed Abdellatif Signature